

## SPEED 400

### Electrical System

| Part Number                     | Description                            | Korean Price | Req | Comment                           |
|---------------------------------|----------------------------------------|--------------|-----|-----------------------------------|
| <b>Alternator &amp; Starter</b> |                                        |              |     |                                   |
| TA351005                        | Stator Assembly                        | ₩401,300     | 1   |                                   |
| TA351017                        | Rotor Assembly                         | ₩937,200     | 1   |                                   |
| LAD00254                        | Bolt, Banjo, M12 x 1.5                 | ₩13,100      | 1   |                                   |
| LDB00105                        | Washer, Plain                          | ₩4,400       | 1   |                                   |
| DK101284                        | Bolt, Skt, M5 x 0.8 x 34,<br>Precoat   | ₩900         | 3   |                                   |
| DH101389                        | Bolt, Socket - M6X1X1 20Xcl 12.9       | ₩1,000       | 4   |                                   |
| LDF00001                        | Washer, Toothed, 6.4 x<br>11.0 x 0.7   | ₩200         | 4   |                                   |
| TA402002                        | Regulator                              | ₩445,300     | 1   |                                   |
| KADA0630                        | Bolt, Flanged, M6 x 1                  | ₩500         | 2   |                                   |
| TA351601                        | Starter Motor                          | ₩355,300     | 1   |                                   |
| TA541209                        | Bracket, Cable, Clutch                 | ₩5,200       | 1   |                                   |
| KADT0625                        | Bolt, Flanged, M6 x 1                  | ₩600         | 2   |                                   |
| YTA02024                        | O Ring                                 | ₩1,000       | 1   |                                   |
| <b>Engine Management</b>        |                                        |              |     |                                   |
| TA351404                        | ECU EMS                                | ₩962,300     | 1   |                                   |
| TA351800                        | Gear Indicator Sensor                  | ₩220,500     | 1   | Includes Crank Position<br>Sensor |
| JG351805                        | Sensor, T Map                          | ₩101,500     | 1   |                                   |
| LBU00045                        | Screw, Btn Hd, M6 x 1<br>x 10, Precoat | ₩500         | 1   |                                   |
| JP351801                        | Pressure Sensor                        | ₩134,600     | 1   |                                   |
| TA351211                        | Ignition Coil Assembly                 | ₩78,800      | 1   |                                   |
| KACA0622                        | Bolt, Socket, M6 x 1                   | ₩600         | 2   |                                   |
| JG351400                        | Temperature Sensor                     | ₩25,300      | 1   |                                   |
| JY351206                        | Spark Plug                             | ₩27,800      | 1   |                                   |
| JP351209                        | Grommet, Spark Plug                    | ₩600         | 1   |                                   |
| TA541216                        | Bracket, Harness                       | ₩3,300       | 1   |                                   |
| LAE00010                        | Bolt, Flanged, M5 x 0.8                | ₩300         | 3   |                                   |
| TA541032                        | Plate, Harness                         | ₩3,800       | 1   |                                   |
| JP591065                        | Oxygen Sensor                          | ₩294,200     | 1   |                                   |
| AA101437                        | Bolt, Flanged, M6 x 1                  | ₩500         | 1   |                                   |
| TA351201                        | Cap Spark Plug                         | ₩24,300      | 1   |                                   |
| JY351203                        | Grommet, Spark Plug Cap                | ₩1,700       | 1   |                                   |
| DD111012                        | Grommet, HT Cable                      | ₩2,300       | 1   |                                   |
| TA351212                        | Cover, Coil Ignition                   | ₩3,800       | 1   | Not Illustrated                   |
| <b>Harness</b>                  |                                        |              |     |                                   |

|                  |                                   |                      |   |                    |
|------------------|-----------------------------------|----------------------|---|--------------------|
| TA402261         | Harness                           | <del>₩</del> 995,000 | 1 |                    |
| JL403000         | Relay, Interlock                  | <del>₩</del> 16,300  | 5 |                    |
| T2500183         | Battery                           | <del>₩</del> 175,900 | 1 | All Except BR & JP |
| T2504606         | Spares Kit, Battery               | <del>₩</del> 154,000 | 1 | BR Only            |
| T2507071         | Battery Kit                       | <del>₩</del> 164,100 | 1 | JP Only            |
| TA402207         | Cable, Harness                    | <del>₩</del> 15,800  | 1 |                    |
| TA402202         | Cable, Relay-Mot                  | <del>₩</del> 36,100  | 1 |                    |
| TA402003         | Starter Relay                     | <del>₩</del> 68,500  | 1 |                    |
| TA401600         | Horn                              | <del>₩</del> 52,300  | 1 |                    |
| LBU00132         | Screw, Btn Hd                     | <del>₩</del> 1,700   | 1 |                    |
| TA403608         | Sensor, Roll Over                 | <del>₩</del> 34,600  | 1 |                    |
| PA181294         | Bolt, Socket Head                 | <del>₩</del> 2,200   | 2 |                    |
| JD402217         | Strap, Cable                      | <del>₩</del> 300     | 2 |                    |
| AA201387         | Clamp, Cable                      | <del>₩</del> 1,300   | 4 |                    |
| 60111420         | Cable Tie Lock                    | <del>₩</del> 500     | 2 |                    |
| LDF00001         | Washer, Toothed, 6.4 x 11.0 x 0.7 | <del>₩</del> 200     | 1 |                    |
| KADD0610         | Bolt, Flanged, M6 x 1             | <del>₩</del> 300     | 1 |                    |
| JG351805         | Sensor, T Map                     | <del>₩</del> 101,500 | 1 |                    |
| AA201501         | Oil Pressure Switch               | <del>₩</del> 17,700  | 1 |                    |
| DK101340         | O Ring                            | <del>₩</del> 700     | 1 |                    |
| JG402228         | Fuse, Mini, 10A                   | <del>₩</del> 5,700   | 7 |                    |
| JG402229         | Fuse, 15A                         | <del>₩</del> 900     | 5 |                    |
| JG402230         | Fuse, 30A                         | <del>₩</del> 1,200   | 1 |                    |
| TA403402         | Charger, Socket                   | <del>₩</del> 76,700  | 1 | Not Illustrated    |
| TA232627         | Bracket, Cover Ign Switch         | <del>₩</del> 3,300   | 1 | Not Illustrated    |
| LBR00020         | Screw, Tapping Pan Cross, Dia 2   | <del>₩</del> 400     | 2 | Not Illustrated    |
| LBU00222         | Screw, Button Head                | <del>₩</del> 300     | 2 | Not Illustrated    |
| TA181337         | Cover, Ign Switch, Lower          | <del>₩</del> 4,300   | 1 | Not Illustrated    |
| TA181338         | Flap, Socket, USB                 | <del>₩</del> 1,900   | 1 | Not Illustrated    |
| <b>Headlight</b> |                                   |                      |   |                    |
| TA121021         | Holder Headlamp, LH               | <del>₩</del> 41,400  | 1 |                    |
| TA401015         | Headlamp                          | <del>₩</del> 406,900 | 1 |                    |
| TA121022         | Holder, Headlamp, RH              | <del>₩</del> 41,400  | 1 |                    |
| TA121026         | Bracket Assy Holder, Headlamp     | <del>₩</del> 20,300  | 1 |                    |
| TA121025         | Bracket Assembly Holder, Headlamp | <del>₩</del> 20,300  | 1 |                    |
| TA401013         | Holder, Coupler, Headlamp         | <del>₩</del> 2,600   | 1 |                    |
| BF185019         | Clip, Plastic                     | <del>₩</del> 900     | 1 |                    |
| TA121024         | Damper                            | <del>₩</del> 900     | 2 |                    |
| LBU00181         | Screw, Btn Hd, M8 x 1.25          | <del>₩</del> 1,400   | 2 |                    |
| LBU00190         | Screw, Btn Hd, M6 x 1             | <del>₩</del> 1,200   | 4 |                    |
| KADD0516         | Bolt, Flanged, M5 x 0.8           | <del>₩</del> 300     | 2 |                    |

|                    |                                     |                      |   |                                |
|--------------------|-------------------------------------|----------------------|---|--------------------------------|
| LDB00039           | Washer, Plain, ID 5.5 x OD 16 x 1.2 | <del>₩</del> 200     | 2 |                                |
| TA181308           | Grommet                             | <del>₩</del> 600     | 2 |                                |
| TA181310           | Cable Guide                         | <del>₩</del> 500     | 1 |                                |
| <b>Indicators</b>  |                                     |                      |   |                                |
| TA401002           | Indicator, Front, LH                | <del>₩</del> 79,300  | 1 | All Expt US                    |
| TA401018           | Indicator, Front, LH                | <del>₩</del> 79,300  | 1 | US Only                        |
| TA401003           | Indicator, Front, RH                | <del>₩</del> 79,300  | 1 | All Expt US                    |
| TA401019           | Indicator, Front, RH                | <del>₩</del> 79,300  | 1 | US Only                        |
| TA401004           | Indicator, Rear, LH                 | <del>₩</del> 79,300  | 1 | All Expt US                    |
| TA401025           | Indicator, Rear, LH                 | <del>₩</del> 79,300  | 1 | US Only                        |
| TA401005           | Indicator, Rear, RH                 | <del>₩</del> 79,300  | 1 | All Expt US                    |
| TA401026           | Indicator, Rear, RH                 | <del>₩</del> 79,300  | 1 | US Only                        |
| TA401011           | Front Indicator Stay, LH            | <del>₩</del> 29,700  | 1 |                                |
| TA401012           | Front Indicator Stay, RH            | <del>₩</del> 29,700  | 1 |                                |
| LAC00226           | Bolt, Socket, M6 x 1                | <del>₩</del> 900     | 2 |                                |
| <b>Instruments</b> |                                     |                      |   |                                |
| TA402400           | Instrument Cluster, MPH             | <del>₩</del> 893,800 | 1 | UK & US Markets                |
| TA402431           | Instrument Cluster, KPH             | <del>₩</del> 893,800 | 1 | All Except UK & US Markets     |
| TA402425           | Bracket, Holder, Speedometer        | <del>₩</del> 14,500  | 1 |                                |
| TA113863           | Grommet                             | <del>₩</del> 1,000   | 3 |                                |
| LDB00039           | Washer, Plain, ID 5.5 x OD 16 x 1.2 | <del>₩</del> 200     | 3 |                                |
| KBRA4816           | Screw, Tapping Pan Cross Dia 4.8    | <del>₩</del> 300     | 3 |                                |
| LBU00203           | Screw, Btn Hd, M6 x 1               | <del>₩</del> 1,900   | 2 |                                |
| <b>Lockset</b>     |                                     |                      |   |                                |
| TA232600           | Set Lock                            | <del>₩</del> 833,000 | 1 |                                |
| T2505838           | Key, Cut                            | <del>₩</del> 146,800 | 1 |                                |
| YTA04005           | Key, Blank                          | <del>₩</del> 104,900 | 1 |                                |
| LBU00231           | Button Hd Screw                     | <del>₩</del> 400     | 2 |                                |
| JL232604           | Cover, Latch                        | <del>₩</del> 1,400   | 1 |                                |
| KADF0625           | Bolt, Flanged, M6 x 1               | <del>₩</del> 600     | 2 |                                |
| TA232608           | Seat Latch Assembly                 | <del>₩</del> 15,300  | 1 |                                |
| TA232606           | Seat Latch Cable                    | <del>₩</del> 8,300   | 1 |                                |
| DH101386           | Hex Bolt, Flgd                      | <del>₩</del> 600     | 2 |                                |
| TA232602           | Bracket, Lock                       | <del>₩</del> 3,000   | 1 |                                |
| <b>Rear Light</b>  |                                     |                      |   |                                |
| TA401001           | Tail Lamp                           | <del>₩</del> 60,000  | 1 |                                |
| KBUA0610           | Screw, Truss, M6 x 1                | <del>₩</del> 300     | 1 |                                |
| KCGA0606           | Nut, Hex, Flanged                   | <del>₩</del> 200     | 2 |                                |
| 39150811           | Washer, Plain                       | <del>₩</del> 200     | 1 |                                |
| JB401012           | Foam                                | <del>₩</del> 400     | 1 |                                |
| TA181447           | Bracket, Reflex Reflector           | <del>₩</del> 15,500  | 1 | US & ID Only - Not Illustrated |

|          |                     |                     |   |                                |
|----------|---------------------|---------------------|---|--------------------------------|
| TA401016 | Reflex Reflector    | <del>₩</del> 8,600  | 1 | US & ID Only - Not Illustrated |
| TA401014 | Reflex Reflector    | <del>₩</del> 11,800 | 1 | Part Not Illustrated           |
| TA401006 | Number Plate Lamp   | <del>₩</del> 56,900 | 1 | Not Illustrated                |
| KDBB0613 | Plain Washer        | <del>₩</del> 200    | 2 | Not Illustrated                |
| KCGA0505 | Nut, Hex Flgd       | <del>₩</del> 200    | 2 | Not Illustrated                |
| LBR00003 | Screw, Tapping, Pan | <del>₩</del> 200    | 2 | Not Illustrated                |
| 30211005 | Collar              | <del>₩</del> 900    | 2 | Not Illustrated                |
| DD201011 | Damper              | <del>₩</del> 700    | 2 | Not Illustrated                |
|          |                     |                     |   |                                |